

Oil Field Environmental Incident Summary

Incident: 20140605170121 **Date/Time of Notice:** 06/05/2014 17:01

Responsible Party: ONEOK Rockies Midstream

Well Operator: ONEOK ROCKIES MIDSTREAM

Well Name: Charlson Compressor Station

Field Name:

Well File #:

Date Incident: 6/4/2014

Time Incident: 19:30

Facility ID Number:

County: MCKENZIE

Twp: 153

Rng: 95

Sec: 21

Qtr:

Location Description: 10546 44th Street NW, New Town, ND 58763

Submitted By: Mitch Anderson

Received By:

Contact Person: Mitch Anderson
2700 Lincoln Avenue SE
Sidney, MT 59270

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1 Mile

Distance Nearest Water Well: 1 Mile

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	2	Barrels	2	Barrels		

Description of Other Released Contaminant:

Natural Gas Liquids (Condensates) & Water

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

There were no immediate health hazards to workers or the general public.

Areal Extent:

The liquids were completely contained inside the compressor building.

Potential Environmental Impacts:

There were no adverse environmental impacts.

Action Taken or Planned:

The high pressure release was completely contained within the Charlson compressor building.

Wastes Disposal Location: At a licensed and approved landfill

Agencies Involved:

Updates

Date: 6/6/2014 **Status:** Reviewed - No Action Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

High pressure release of natural gas liquids was contained within the compressor building. No fluids escaped the building. No followup is necessary.